## PRODUCT CHANGE NOTIFICATION

Date: March 12<sup>th</sup>, 2012

PCN: PCN LEDIL025

Subject: Mechanical issue between BROOKE-SCR series and Citizen CLL030

LEDs.

Description: LEDiL found in mechanical inspection that solder pads of Citizen

CLL030 LEDs are too close to emitting area and there is not enough

space for BROOKE-SCR series of reflectors.

Time line: This Product Change Notification is valid immediately.

Part numbering: C12083\_BROOKE-SCR-M

C12084\_BROOKE-SCR-W

Above part numbers have been discontinued from product selection of

Citizen CLL030 with no replacement

Contact information: Sampsa Nurmi

LEDIL Oy Salorankatu 10 24240 SALO FINLAND

sampsa.nurmi @ ledil.com